



1826 Kramer Lane, Suite M
 Austin, Texas 78758
 p | 512-926-6650
 f | 512-833-5058
 kleinfelder.com

To: Yarrington Road Materials
 Attn.: Mr. Chase Coleman
 P.O. Box 967
 Kyle, Texas 78640

Project: 2013 Yarrington Road QA

Project No.: 110038
Date: 4-09-13
Control No.: 040914 C


REPORT OF: Sieve Analysis
TEST METHOD: TEX-401A
LAB ID NUMBER: G-3476
MATERIAL DESCRIPTION: Washed Concrete Sand
MATERIAL SOURCE: Plant
SAMPLED BY: Client
DATE SAMPLED: 4-04-13
TEST PERFORMED BY: D. Potteiger, ACI# 01147441
RESULTS:

<u>Sieve Size</u>	<u>Percent Passing</u>	<u>TxDOT Item 421</u>	<u>ASTM C-33</u>
3/8"	100	100	100
#4	97.2	95-100	95-100
#8	87.1	80-100	80-100
#16	66.0	50-85	50-85
#30	42.5	25-65	25-60
#50	19.9	10-35	5-30
#100	5.8	0-10	0-10
#200	2.9	0-3	0-3

Fineness Modulus.....2.82 (2.30-3.10)

1-Above

Report Reviewed by: BS


 Barry Siler, C.E.T.

Pursuant to applicable building codes, the results presented in this report are for the exclusive use of the client and the registered design professional in responsible charge. The results apply only to the samples tested. If changes to the specifications were made and not communicated to Kleinfelder, Kleinfelder assumes no responsibility for statements (meets/does not meet), if provided. If the samples tested were sampled and/or transported to our laboratory by parties other than Kleinfelder staff, this report makes no representation of whether the samples are representative of the material onsite.