



1826 Kramer Lane, Suite M
Austin, Texas 78758
p | 512-926-6650
f | 512-833-5058
kleinfelder.com

To: Yarrington Road Materials
Attn.: Mr. Chase Coleman
P.O. Box 967
Kyle, Texas 78640

Project: 2010-12 Yarrington Road QA


Project No.: 110038
Date: 10-18-12
Control No.: 101804 C

Page 1 of 1

REPORT OF: Sieve Analysis of Fine Aggregates
TEST METHOD: ASTM C136
LABORATORY ID#: G-3376
MATERIAL DESCRIPTION: River Sand
LOCATION SAMPLED: Plant Stockpile
MATERIAL SAMPLED BY: Client
DATE RECEIVED: 10-05-12
TEST PERFORMED BY: D. Potteiger, ACI #01147441; T. Weathers
RESULTS:

<u>Sieve</u>	<u>% Passing</u>
3/8"	100
#4	99.6
#10	99.1
#40	89.7
#200	72.8

Report Reviewed by: res


Barry Siler, C.E.T.

The results shown on this report are for the exclusive use of the client for whom they were obtained and apply only to the samples tested and/or inspected. They are not intended to be indicative of the qualities of apparently identical products. The use of our name must receive our prior written approval. Reports must be reproduced in their entirety.